

# General Environmental Incident Summary

**Incident:** 8040

**Notice:** 4/12/2019 1030

**Occurred:** 4/9/2019 1630

**DEM Incident No:**

**No Further Action:** ☒

**Responsible Party:** Harlow's Bus Sales

**County:** Burleigh

**Twp Rng Sec Qtr:** 138 80 1

**Lat Long + Method:** 46.80418 -100.72730 Interpolation from map

**Location Description:** Bismarck fairgrounds east of Bismarck just south of the 4H building

**Submitted By Info:** Jerry Schaff  
employee  
1806. Schaff Drive  
Mandan ND 58554

**Received By Info:**

**Contact Info:** Jerry Schaff  
1021 S.23rd. Str  
Bismarck ND 58504

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 750 Feet

**Type of Incident:** ruptured fuel line on Bus

**Release Contained:** Yes

**Reported to NRC:** No

**Contaminant:** Diesel fuel

**Volume of Release:** 15 gallons

**Duration of Release:** 12 hours

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** No

**Number of Fatalities:** 0

**Number of Injuries:** 0

**Cause of Incident:**

Fuel supply line from tank to fuel filter ruptured (aged) and leaked out onto the ground over night. Spill was found the following morning and the hose repaired.

**Risk Evaluation:**

none

**Potential Env. Impacts:**

small area of grass about 20sq ft of grass will be destroyed due to spill and excavation

**Action Taken/Planned:**

The hose was repaired and the leak stopped as soon as it was discovered, however the proper people were NOT notified of the spill so clean up was not immediate. It is our intent (if approved) to excavate all of the visual contaminated soil approximately 2 cubic yards and spread it over a few acres and aerate the soil. Unless there would be an approved site where it could be dumped.

**Wastes Disposal Location:**

1021 S. 23rd Str

**Other Agencies Involved:**

Bismarck Park Board

## **Updates**

---

**Date:** 4/11/2019      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Notes:**

According to the report, 15 gallons of diesel fuel was released onto area soils. Further follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 4/11/2019      **Status:** Inspection

**Author:** O'Gorman, Brian

**Notes:**

Arrived on location at 16:45. Drove around parking area and took photos. Did not notice the impacted area during the inspection. Photos added to the incident folder. More follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 4/12/2019      **Status:** Correspondence - More Follow-up Required

**Author:** Stockdill, Scott

**Notes:**

Email from Responsible party.

"...Scott, I have attached pictures of the fuel spill at the fairgrounds on the east side of Bismarck. Please guide me through the process in which you would like me to follow for clean up...."

Full email and photos in report folder.

More follow up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 4/12/2019      **Status:** Correspondence - More Follow-up Required

**Author:** Stockdill, Scott

**Notes:**

Email from responsible party.

"... Thank You, I will take pictures after exaction and after the site is reclaimed and forward them to you next week. ..."

Full email in report folder.

More follow up is necessary.

**Updated Volume:** None at the time of this update

---

**Date:** 4/15/2019      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received a phone call from the company contact. The contact wanted to discuss what we would need in order to cleanup the location. Contact emailed me his information. Email added to the incident folder. More follow-up needed.

**Updated Volume:** None at the time of this update

---

**Date:** 4/15/2019      **Status:** Inspection

**Author:** Sandvick, Duane

**Notes:**

Inspection 4-15-2019  
Time: 1;15 pm CDT

There was evidence of a petroleum product spill in the ditch. No clean up activity had been done. Photos were taken.  
Further follow up needed

**Updated Volume:** None at the time of this update

---

**Date:** 5/14/2019      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received an email from the company's consultant with a cleanup report attached. Review of the report showed that the impacted soils had been removed and the confirmation sample was below UST cleanup guidelines. An on-site visual should be conducted later this summer for proper vegetative re-growth. More follow-up needed. Email and report added to the incident folder.

**Updated Volume:** None at the time of this update

---

**Date:** 8/21/2019      **Status:** Correspondence

**Author:** O'Gorman, Brian

**Notes:**

Received an email from the company contact with a photo showing good coverage for plant growth in the area remediated. No further follow-up needed at this time. Email and photo added to the incident folder.

**Updated Volume:** None at the time of this update